



Product information

Weller®

KH E

Code No. : **T0051507699**

Active Safety Rest with Stop+Go for FE Irons

Basic Unit Electric (for WFE P) Stop+Go + Safety Rest Function with Fibre Optic Sensor for FE 75 and FE 80.



This safety rest is ESD safe.

Basic unit electric (for WFE P) safety rest with Stop+Go function with fibre optic sensor for FE 75 and FE 80

The Weller safety rests with Stop+Go function are recommended accessories for FE irons using the WFE or WFE P extraction units. A fibre optic sensor switches the extraction unit on when the FE iron is removed from the safety rest and when the FE iron is replaced in the safety rest, after a short delay to gather the fumes from any solder on the tip it switches the unit off. This reduces running costs.