

SEMIKRON Elektronik GmbH & Co. KG · Sigmundstr. 200 · 90431 Nuremberg

To whom it may concern

Nuremberg, 25<sup>nd</sup> Jan. 2018

**Diode modules SKKD 26/.., SKKD 46/.., SKKD 81/.., SKKH 27/.., SKKH 42/.. and SKKH 57/..:  
Unusual technical phenomenon in final function test, Replacement of stock**


Dear Sirs,

Following our communication dated 18<sup>th</sup> January 2018 concerning SEMIPACK 1.5 modules.

Our quality division continues to investigate the unusual technical phenomenon during the production tests of the affected SEMIPACK 1.5 modules.

As a precautionary measure, in order to mitigate potential risks for you and your customers, we would like to offer you, based on good-will, without prejudice and without assuming any responsibilities, replacement of the affected Semipack from your stock. We will arrange to send replacement for these lots shortly. Please bear with us and contact your local sales responsible from Semikron or partnering distributor in order to start the process.

We sincerely regret and apologize for any inconvenience caused to you and your customers.



Marcus Neckermann  
Head of Quality International

James Willford  
Head of Sales Germany