

PRODUCT CHANGE NOTICE (PCN)

PCN#	WPC-140610-001	Issuing Date	June 10, 2014
-------------	----------------	---------------------	---------------

PRODUCT(S) AFFECTED :

Attachment: Yes No

WIZ107SR, WIZ108SR		
Hardware	Firmware	Supplying Schedule
N/A	4.02 -> 4.03	From April 15, 2014
W7100-S2E-100 / W7100-S2E-64		
Hardware	Firmware	Supplying Schedule
N/A	3.14 -> 4.03	From June 10, 2014

Description of Change

1. WIZ107SR / WIZ108SR
 - Fixed DHCP parser error when processing DHCP option field 0
 - Fixed the error that Ethernet to UART operates even if the remote IP address is not correctly set
2. W7100-S2E-100 / W7100-S2E-64
 - Follows all changes of WIZ107SR Firmware

DISTRIBUTORS NOTIFICATION :

The purpose of this note is to inform changes in the Firmware of WIZ107SR module & W7100-S2E-100 & W7100-S2E-64 chips. The purpose of all changes are for better performance and convenience. There is no difference in all functions and features.

Please notify this change to the customers who are using the upgraded products.

If you have any questions, please contact sales@wiznet.co.kr or support@wiznet.co.kr

DISTRIBUTOR ACKNOWLEDGEMENT : Distributors may use this form to acknowledge receipt of this notification. Please fill in the below form and return it to us.

Distributor		Date	
Name		Title	
E-mail			
Comments			