



## Product information

# Weller®

**KHEP**Code No. : **T0051516172**

Active toolholder w/FE

Second safety rest with fibre optic sensor for extending to 2 workplaces for WSP 80 FE

The Weller Zero-Smog Systems put an end to air pollution caused by soldering, adhesives and laser work. In all of these applications fumes or fine particles are released into the work place atmosphere which are hazardous to staff exposed to them. The Weller Zero-Smog Systems' combination of pumps, electronic controls and filters removes this hazard.



This safety rest is ESD safe.

Second safety rest with fibre optic sensor for extending to 2 workplaces.

The Weller safety rests with Stop+Go function are recommended accessories for FE irons using the WFE or WFE P extraction units. A fibre optic sensor switches the extraction unit on when the FE iron is removed from the safety rest and when the FE iron is replaced in the safety rest, after a short delay to gather the fumes from any solder on the tip it switches the unit off. This reduces running costs.